



ITEM NO.	QTY.	PART NO.	DESCRIPTION
1	1	015878	ASSEMBLED V2 PISTON
2	1	015879	ASSEMBLED V2 GUIDE BUSHING
3	1	000552	5/8-18 SAE HEX FIN NUT
4	1	015175	1-5/8" INTERNAL SPIRAL RING-V2
5	2	000508	3/8-16x3/4" HHCS GR5
6	2	000575	3/8" USS FLAT WASHER
7	1	016199	7/8" CYLINDER SHAFT PROTECTIVE SLEEVE
8	1	013675	CYLINDER PORT ASSEMBLY PLUG
9	2	015522	HEX PIN (V2) ZINC PLATED
10	1	009077	3/16"x7-1/2" CABLE TIE
11	1	095265	V2 CYLINDER REPAIR OR REPLACEMENT INSTRUCTIONS



NOTE: THIS KIT IS NOT COMPATIBLE WITH CYLINDERS THAT HAVE A Ø3/4" SHAFT

NOTE: ACCOUNTING DO NOT INCLUDE 16199 IN BOM

E	7/6/22	REPLACED 017657 WITH 000508	AAS		2770	THIRD ANGLE PROJECTION  UNLESS OTHERWISE SPECIFIED DIMENSIONS ARE IN INCHES TOLERANCES: FRACTIONAL ±1/16 ANGULAR MACH ±1° BEND ±1° TWO PLACE DECIMAL ±0.030 THREE PLACE DECIMAL ±0.010	DRAWN BY GDB DRAWN/DATE 12/17/18 APPVD/DATE — DO NOT SCALE DRAWING	NOTES: _____ _____ _____ _____ TITLE V2 CYLINDER SEAL REPAIR KIT	WOODBINE MFG. CO. BUS BROWN DRIVE WOODBINE, IOWA 51579 		
D	1/26/22	REPLACED 000737 WITH 017657	JRR		2708						
C	8/1/19	ADDED COMPATABILITY NOTE, 16199 WAS 763	GDB		2221						
B	3/15/19	ADDED (2) 015522, AND (1) 009077	GDB		2198						
A	12/17/18	RELEASED TO PRODUCTION	GDB		2147						
REV.	DATE	CHANGE RECORD	BY	APPVD	ECN	THE INFORMATION HERE IS CONFIDENTIAL AND MUST NOT BE USED IN ANY WAY DETRIMENTAL TO THE INTEREST OF WOODBINE MFG.			SCALE 1: 4	WEIGHT —	PART NO. 15880